



The condition of power poles after the thunderstorm. SE Pic

Thunderstorm snaps power supply in Pakyong subdivision

Sikkim
Express
11/04/21

AJAY THAMI

PAKYONG, April 10: Power supply in different parts of Pakyong subdivision has snapped after electricity lines and poles were damaged during the Friday evening thunderstorm.

Power supply has been restored in some places and it will take three-four days to restore in all places, informed DE (Power) Binoy Sharma. Since morning, the Power staff

and engineers are at the field to restore power supply, he said.

Standing crops were also lost during the intense rainfall and hailstones at Namcheybong and Lossing villages. Trees were uprooted

at different places while some houses have been reported as damaged.

We are in the field since morning to assess the damage caused by the thunderstorm and hailstones, informed the Pakyong SDM.

