Copy for kind info. to:

Total

i. The Chief Secretary, Govt. of Sikkim.

ii. The Secretary to the Hon'ble Governor.

iii. Secretary to HCM, Office of the HCM.

iv. The PS to HM, LR&DM Deptt.

90

v. The Secretary/IPR.

vi. The DC, Gangtok/Mangan/Pakyong/Namchi.

87300

37



3438

21

Land Revenue & Disaster Management Department Government of Sikkim, Gangtok

3773



16

DETAIL LIST OF RELIEF CAMPS AND INMATES PRESENTLY STAYING IN THE RELIEF CAN
PS .

	iotal		Namchi	Pakyong	Dakwong		Gangtok		Mangan	Districts
	Relief Camps - 21 Nos. Inmates in Relief Camps - 3773	i. Pranami Mandir, Namphing - 348 ii. Recep Primary School – 24 iii. NHPC Primary School Linkutar - 33	03 Nos	i. Chanatar Govt Secondary School -302 ii. Majhitar Govt. Secondary School & Mining Govt Sr. Sec School - 87 iii. Majhigaon Housing Complex - 223 iv. Golitar Nepali Dharamshala - 255 v. Eco Paradise - 52		 iii. Food Preservation Factory – 15 iv. Pranami Mandir Singtam – 64 v. Masjid Singtam – 143 vi. Singtam Church – 92 vii. Medhavi Skill University - 52 viii. Marwari Dharamshala - 75 	i. Singtam Govt. Sr. Sec School - 548 ii. Bihari Bhawan- 576	iv. Chungthang Gumpa – 80 v. Chungthang Gurudwara- 250	05 Nos. i. ITI, Chaday - 65 ii. Naga – 289 iii. Community Hall, Bob - 200	No. of Relief Camp Operational
Cand Revenue & Disaster Management Department Government of Sikkim, Gangtok	11430	ii. Sewerage Treatment Plant and pipelines washed away in Melli. III. Steel Foot bridge over Teesta River connecting 20 th Mile to Chalamthang in Namchi District. iv. Steel Bridge connecting Kabrey, Namchi District to Majitar in Gangtok District. v. Steel Foot bridge of Lanco Pvt. Ltd over Teesta River connecting Pamphok (Thalthaley to Tar Khola, WB)	i. LD Kazi Bridge washed away.	 i. Sewerage Treatment Plant and pipelines washed away in Rangpo. ii. NH-10 has sustained extensive damages. iii. IBM totally submerged in floods, Rangpo, Baghey Khola, Majhitar, Bardang are severely affected by . iv. Baghey Khola River side habitations have been submerged. v. Course of Teesta River changed and caused extensive damage to the properties at various locations. vi. Power Supply lines have been damaged extensively. vii. PHE/ Storage along with pipelines are extensively damaged at IBM and Golitar. 	Sowers Treatment Plant and sinclines worked area in Page 1	iv. Sneha Kinetic Powerhouse and NHPC dam site have been submerged. v. Balutar bridge washed away and extensive damages of State Highway along Balutar/Sirwani/ Goshkhan Area.	i. Indreni Bridge in Singtam washed out. ii. NH -10 highway has sustained extensive damage. iii. Sewage Treatment plant and pipelines washed in Singtam.	 v. Office of the Range Officer Territory Damaged at Dzongu. vi. Moon Light Private School Building/ Forest store. vii. Naga/Power Office and Quarter damaged. xii. Lepcha Traditional House washed away. viii. Namprickdang Playground Gallery & 3 units RCC toilet damage. xiv. Firing Bridge at Chungthang. 	i. Chungthang Sikkim Urja Dam washed away. ii. Toong Naga GPU affected. iii. Toong Naga GPU affected. iii. Road damaged between Toong and Naga. vi. Police Office Quarter, Pass-Permit Entry Check Post & Fire Office Damaged at Phidang.	Loss and Damage to Infrastructure