## Report on Extent of Damage due to Cloudburst Induced Flooding in the Teesta Basin as on 11.00 Hrs. 13 th OCTOBER 2023 Animal No of No. of No. of No of No of People **Partially Partially** No. of **Fully** and No. of No of No. of Persons No. of No. of Name of Relief **Inmates** and **Bridges Evacuated** people Damaged Damaged **Damaged** Severely **Population** Human who suffered Villages / people **Poultry** washed in Relief Camps Rescued Kutcha damaged Pucca Houses grievous injury affected **Lives Lost** missing Wards/ Districts Camps Lost awav Opened House House Pucca and requiring Nagar affected Kutcha hospitalization **Panchayat** House / Councils affected 16 15 14 13 12 11 9 10 • 7 8 6 3 4 5 2 1 Animal -2456 997 People evacuated Poultryby Chopper/Foot 04 03 303 850 91 96 26 434 247 6653 Tourists Locals 04 17 (02 - Indian 50 30300 Mangan Others-Army) 1767 257 507 Animal -106 03 08 1531 1025 1025 30 48 Poultry-319 241 Gangtok 25 05 07 20000 19 7943 Animal-303 14 + 1005 919 58 58 635 Poultry -635 21 30 07 30000 (Indian Pakyong 8987 Army) Animal -316 04 375 03 630 45 137 630 482 300 Poultry -Namchi 06 02 8100 23 2125 3128 33 19 4169 2563 166 281 1870 1423 30 78 37

Copy for kind info. to:

Total

i. The Chief Secretary, Govt. of Sikkim.

ii. The Secretary to the Hon'ble Governor.

iii. Secretary to HCM, Office of the HCM.

iv. The PS to HM, LR&DM Deptt.

99

v. The Secretary/IPR.

vi. The DC, Gangtok/Mangan/Pakyong/Namchi.

88400



Secretary-cum-State Relief Commissioner Land Revenue & Disaster Management Department Government of Sikkim, Gangtok



Districts	No. of Relief Camp Operational	Loss and Damage to Infrastructure
Mangan	i. ITI, Chaday - 64 ii. Naga – 157 iii. Chungthang Gurudwara- 82	i. Chungthang Sikkim Urja Dam washed away. ii. Toong Naga GPU affected. iii. Road damaged between Toong and Naga. vi. Police Office Quarter, Pass-Permit Entry Check Post & Fire Office Damaged at Phidang. v. Office of the Range Officer Territory Damaged at Dzongu. vi. Moon Light Private School Building/ Forest store. vii. Chungthang 4 no. RCC Foot- bridge washed away. viii. Lachung Dzomsa 2 no. RCC Foot Bridge washed away. ix. Passingdong 1 no. RCC Foot Bridge washed away. ix. 80% of Chungthang Town severely affected. xii. GREF crusher plant and Toong Police Check-post. xiii. Forest Guest House, Namprikdang. xiiii. Forest G
Gangtok	<ul> <li>08 Nos.</li> <li>i. Singtam Govt. Sr. Sec School - 541</li> <li>ii. Bihari Bhawan- 572</li> <li>iii. Food Preservation Factory – 15</li> <li>iv. Pranami Mandir Singtam – 74</li> <li>v. Masjid Singtam – 111</li> <li>vi. Singtam Church – 92</li> <li>vii. Medhavi Skill University - 57</li> <li>viii. Marwari Dharamshala - 69</li> </ul>	x. Namprickdang Playground Gallery & 3 units RCC toilet damage. xix. Firing Bridge at Chungthang.  i. Indreni Bridge in Singtam washed out.  ii. NH -10 highway has sustained extensive damage.  iii. Sewage Treatment plant and pipelines washed in Singtam.  iv. Sneha Kinetic Powerhouse and NHPC dam site have been submerged.  v. Balutar bridge washed away and extensive damages of State Highway along Balutar/Sirwani/ Goshkhan Area.
akyong	i. Chanatar Govt Secondary School -302 ii. Majhitar Govt. Secondary School & Mining Govt Sr. Sec School - 87 iii. Majhigaon Housing Complex - 223 iv. Golitar Nepali Dharamshala - 255 v. Eco Paradise - 52	<ul> <li>i. Sewerage Treatment Plant and pipelines washed away in Rangpo.</li> <li>ii. NH-10 has sustained extensive damages.</li> <li>iii. IBM totally submerged in floods, Rangpo, Baghey Khola, Majhitar, Bardang are severely affected by .</li> <li>iv. Baghey Khola River side habitations have been submerged.</li> <li>v. Course of Teesta River changed and caused extensive damage to the properties at various locations.</li> <li>vi. Power Supply lines have been damaged extensively.</li> <li>vii. PHE/ Storage along with pipelines are extensively damaged at IBM and Golitar.</li> <li>viii. Under construction bridge at Golitar, Singtam has been damaged.</li> </ul>
Namchi	03 Nos i. Pranami Mandir, Namphing - 318 ii. Recep Primary School – 24 iii. NHPC Primary School Linkutar - 33	i. LD Kazi Bridge washed away. ii. Sewerage Treatment Plant and pipelines washed away in Melli. III. Steel Foot bridge over Teesta River connecting 20 <sup>th</sup> Mile to Chalamthang in Namchi District. iv. Steel Bridge connecting Kabrey, Namchi District to Majitar in Gangtok District. v. Steel Foot bridge of Lanco Pvt. Ltd over Teesta River connecting Pamphok (Thalthaley to Tar Khola, WB)
otal	Relief Camps - 19 Nos. Inmates in Relief Camps – 3128	Secretary um-State Relief Commissioner  Secret

