Inspection of landslides and road issues of Chongrang

SE Report

GANGTOK, February 16: monastery where the absence As per direction of Geyzing of drainage along the roads DC Yishey D. Yongda, a field have caused major devastation visit under Chongrang block during torrential rains of last was conducted today for monsoon. They also inspected sorting out various roads, damaged houses, power drainage, power and cabling requirements at the

inspection was carried out by the monastery.

inspection team were informs.

Gerethang, Lower Chongrang, Nerdang and Tashiding calamities related issues. monasery and the recently The day long joint black-topped road leading to

a team comprising of The team would be engineers, zilla and ward submitting a detailed report to panchayats concerned. the district collector, an IPR The areas covered by the release from Geyzing

